
REPAIRS:

1996-2000 Civic 1988-1991 Civic/CRX 1992-1995 Civic / Del sol TIME FASTENER COMPANY 5301 unit G Longley lane Reno Nevada 89511 (800) 423-4070 (775) 829-1026 www.timesert.com



STEP 1

PLACE LARGEST HOLE IN DRILL FIXTURE OVER THE HOLE TO BE REPAIRED. PLACE LINE PLUG IN LARGEST HOLE TO ALIGN WITH DAMAGED HOLE. DO NOT FORCE LINE PLUG INTO HOLE. USE 2 BOLTS AND TIGHTEN TO SECURE FIXTURE IN PLACE. PLATE CAN BE FLIPPED OVER FOR CORRECT ALIGNMENT. REMOVE ALINEMENT PLUG.

STEP 2 PLACE DRILL BUSHING IN FIXTURE PLATE.

USE A SUITABLE DRILL MOTOR AND STEP DRILL THE HOLE UNTIL THE <u>APPROPRIATE STOP COLLAR</u> ON THE DRILL LINES UP WITH THE TOP OF THE DRILL BUSHING. THIS WILL REQUIRE REMOVING DRILL AND BUSHING SEVERAL TIMES TO CLEAR CHIPS. CLEAN OUT ALL CHIPS. <u>WATCH CAREFULLY THAT THE CORE DRILL IS GOING STRAIGHT!</u> THIS IS VERY IMPORTANT. NOTE: If drill bushing turns while drilling hole, Remove drill and drill bushing, Clean out all chips. We recommend using a long air nozzle 6" or longer to blow out all chips.

STEP 3 (USE WD40 for tapping)

TAP THROUGH THE DRILL BUSHING UNTIL THE <u>APPROPRIATE GROOVE</u> ON THE TAP LINES UP WITH THE TOP OF THE DRILL BUSHING. THIS WILL REQUIRE REMOVING THE TAP AND BUSHING SEVERAL TIMES TO CLEAR CHIPS. CLEAN ALL CHIPS USING BRAKE OR CONTACT CLEANER THAT WILL NOT LEAVE AN OILY RESIDUE, THE HOLE MUST BE CLEAN AND DRY. USE A FLASHLIGHT TO INSPECT THE HOLE FOR CHIPS AND CLEANLINESS.

STEP 4

REMOVE DRILL FIXTURE FOR THE FINAL STEP !

USE INSERT DRIVER OIL (DO NOT USE Wd40.)

OIL THE THREADS OF THE INSERT DRIVER. SCREW AN INSERT ONTO THE DRIVER, APPLY A SMALL AMOUNT OF LOCTITE 266 ON THE BOTTOM OUTSIDE THREADS OF THE INSERT AND SCREW THE INSERT INTO THE PREPARED HOLE. WHEN THE HEAD OF THE INSERT IS SEATED THE DRIVER WILL TIGHTEN UP, USE A LITTLE MORE POWER TO SCREW THE DRIVER THROUGH THE INSERT, UNTIL THE <u>APPROPRIATE GROOVE</u> OF THE DRIVER LINES UP WITH THE <u>TOP OF THE BLOCK.</u> REMOVE INSERT DRIVER, REPAIR IS COMPLETE.

Check for the latest torque specifications before assembling the engine. Improper torque of the head can lead to thread failure.